

# Fax Cover Sheet

**GREG A GRUBE**

**10430 LANC-NEWARK RD.  
MILLERSPORT OHIO 43046**

**740-467-2223  
FAX 740-862-8503**

Send to: <i>John KRANER</i>	From: <i>Capt. GRUBE</i>
Attention: <i>John KRANER</i>	Date: <i>7-16-04</i>
Office location: <i>City of Lancaster Fire</i>	Office location:
Fax number: <i>740 681 5008</i>	Phone number: <i>(740) 808 - 1058</i>

Urgent    Reply ASAP    Please comment    Please review    For your information

Total pages, including cover: *7*

**Comments:**

*St Rt 37 + 256 auto accident  
w/ fuel spill.  
Van Driver Flown out by med Flight  
Semi Driver Non injured*



# OHIO FIRE INCIDENT REPORTING SYSTEM

# INCIDENT REPORT

1  DELETE  
2  CHANGE

Fire Department Thurston Walnut Twp F.D.

FDID <u>2130219</u>	INCIDENT NO.	EXP.	MO. <u>017</u>	DAY <u>115</u>	YEAR <u>014</u>	DAY OF WEEK 1 Sunday 2 Monday 3 Tuesday 4 Wednesday 5 Thursday 6 Friday 7 Sat <u>5</u>	ALARM TIME <u>11342</u>	ARRIVAL TIME <u>11347</u>	TIME IN SERVICE <u>11611</u>
------------------------	--------------	------	-------------------	-------------------	--------------------	--	----------------------------	------------------------------	---------------------------------

<b>SITUATION FOUND</b> 11-Structure Fire 12-Outside Dollar Loss 13-Vehicle Fire 14-Brush, grass, leaves 15-Trash, Rubbish 16-Explosion, No after fire 17-Outside spill with fire	22-Air Gas. Rupture 32-Emergency Medical call 33-Locked-in trapped 34-Search 35-Extrication 41-Spill, leak-No fire 42-Explosive, Bomb removal 43-Excessive Heat	44-Power line down 45-Arcing electric equipment 46-Aircraft standby 47-Chemical spill 51-Lock-out 52-Water removal 53-Smoke odor removal 54-Animal Rescue	55-Assist Police 56-Unauthorised burning 57-Move-up 59-Other service calls 61-Smoke scare 63-Controlled burn 65-Steam, gas mistaken for smoke 71-Malicious false	72-Bomb Scare 73-Alarm Malfunction 74-Unintentional false 99-Unclassified Other <u>See page 17-19</u>	<b>35</b>
---	--	--	---	---	-----------

<b>ACTION TAKEN</b> 1-Extinguishment 2-Rescue or Assistance 3-Investigation only	4-Remove Hazard 5-Stand by 6-Salvage 7-Ambulance	8-Fill in, Move up 9-Not classified 0-Undetermined	<b>2</b>	<b>MUTUAL AID</b>	1-Rec'd 2-Given N/A	<b>1</b>
---	---	--	----------	-------------------	---------------------------	----------

FIXED PROPERTY USE (Occupancy) Pg 23-43

IGNITION FACTOR Pg 44-45

CORRECT ADDRESS (Up to maximum of 21 characters)  
8010 Lanc-Newark Rd.

ZIP CODE

CENSUS TRACT

OCCUPANT NAME (LAST, FIRST, MI)

TELEPHONE

ROOM or APT.

OWNER NAME (LAST, FIRST, MI)

ADDRESS

TELEPHONE

<b>METHOD OF ALARM</b> 1-Telephone direct 2-Municipal alarm system 3-Private alarm system	4-Radio 5-Verbal 6-No alarm recd. 7-Tie-line (911)	8-Voice signal municipal alarm signal 9-Not classified above 0-Undetermined or not reported	<b>7</b>	<b>CO. INSPECTION DISTRICT</b> <u>620</u>	<b>SHIFT</b> <u>1</u>	<b>NO. ALARMS</b> <u>1</u>
--	---	---	----------	--	--------------------------	-------------------------------

<b>NO. FIRE SERVICE PERSONNEL RESPONDED</b> <u>4</u>	<b>NO. ENGINES RESPONDED</b>	<b>NO. AERIAL APPARATUS RESPONDED</b>	<b>NO. OTHER VEHICLES RESPONDED</b> <u>R, 6, 2, 1</u>
---	------------------------------	---------------------------------------	--

<b>NUMBER OF INJURIES</b>	<b>NUMBER OF FATALITIES</b>
FIRE SERVICE OTHER	FIRE SERVICE OTHER

COMPLEX Pg 61-62

MOBILE PROPERTY TYPE Pg. 63-65 (Complete Line S) NA = 08

AREA OF FIRE ORIGIN Pg 67-68

EQUIPMENT INVOLVED IN IGNITION Pg 71-72 (Complete Line T) 98

FORM OF HEAT IGNITION Pg 74-76

TYPE OF MATERIAL IGNITED Pg 78-79

FORM OF MATERIAL IGNITED Pg 80-81

<b>METHOD OF EXTINGUISHMENT</b> 1-Set extinguisher 2-Make shift aids 3-Portable extinguisher 4-Automatic ext. system	5-Pre-connect hose/tank only 6-Pre-connect hose/hydrant draft standpipe 7-Hand-laid hose/hydrant draft standpipe 8-Master stream device 9-Not classified above 0-Undetermined or not reported	<b>LEVEL OF FIRE ORIGIN</b> 1-Grade level to 9 ft. 2-10 to 19 feet 3-20 to 29 feet 4-30 to 49 feet 5-50 to 70 feet	6-Over 70 feet 7-Objects in light 8-Below ground level 9-Not classified above 0-Undetermined	<b>ESTIMATED TOTAL DOLLAR LOSS</b>
--	--	---	--	------------------------------------

<b>Number of Stories</b> 1-1 story 2-2 story 3-3 to 4 stories	4-5 to 6 stories 5-7 to 12 stories 6-13 to 24 stories	7-25 to 49 stories 8-50 stories or more 0-Number of stories undetermined or not reported	<b>CONSTRUCTION TYPE</b> 1-Fire resistive 2-Heavy timber 3-Protected noncombustible	4-Unprotected noncombustible 5-Protected ordinary 6-Unprotected ordinary 7-Protected wood frame	8-Unprotected wood frame 9-Not classified above 0-Undetermined or not reported
--	---	--	--	--	--

<b>EXTENT OF DAMAGE</b> Confined to the object of origin Confined to part of room or area of origin Confined to room of origin Confined to the fire-rated comp. of origin Confined to floor of origin Confined to structure of origin Extended beyond structure of origin No damage of this type (N/A) Undetermined or not reported	Flame-Smoke 1 1 2 2 3 3 4 4 5 5 6 6 7 7 8 8 9 9 0 0	<b>FLAME</b> <input type="checkbox"/> <b>SMOKE</b> <input type="checkbox"/>	<b>DETECTOR PERFORMANCE</b> 1-Det. in room or space of fire origin - oper. 2-Det. not in rm. or space of fire origin - oper. 3-Det. in rm. or space of origin - no oper. 4-Det. not in rm. or space of origin - not oper. 5-Det. in rm. or space of fire origin but fire too small to oper. 9-Not Classified above 0-Undetermined or not reported 8-No detectors present (N/A)	<b>SPRINKLER PERFORMANCE</b> 1-Equipment operated 2-Equipment should have operated - did not. 3-Equipment pre. but fire too small to oper. 9-Not classified above 0-Undetermined or not reported 8-No equipment present (N/A)
--	---	--	--	---

TYPE OF MATERIAL GENERATING MOST SMOKE Pg 103-104

F SMOKE SPREAD BEYOND ROOM OF ORIGIN

AVENUE OF SMOKE TRAVEL  
1-Air handling duct  
2-Corridor  
3-Elevator shaft  
4-Stairwell  
5-Opening on construction  
6-Utility opening in wall  
7-Utility opening in floor  
8-No avenue of smoke travel (N/A)  
9-Undetermined or not reported

FORM OF MATERIAL GENERATING MOST SMOKE Pg 108-109

IF MOBILE PROPERTY	YEAR	MAKE <u>Ford</u>	MODEL <u>Windstar</u>	SERIAL NO. <u>DR09110</u>	LICENSE NO. <u>EV7466</u>
IF EQUIPMENT INVOLVED IN IGNITION	YEAR	MAKE	MODEL	SERIAL NO.	

MEMBER MAKING REPORT Eric Russell FF DATE 7-15-04 OFFICER IN CHARGE (if different) Capt. GREG GRUBE DATE 7-15-04

Remarks Driver of semi contacted BBU Services for Cleanup. EMA + EPA were contacted and responded. to scene

GRASS, TRASH FIRES, SHORT FORM

COMPLETE FOR ALL INCIDENTS

COMPLETE FOR ALL FIRES

COMPLETE IF STRUCTURE FIRE

THE  
2 GARRETT

ING

CONNECT 1200

FAIRFIELD COUNTY SHERIFF  
TRANSACTION REPORT

Page 1

7/15/04

13:38

Date: 07/15/04 Time: 13:38 Call Taker/Dispatcher: 040/D19 Number: 1316648  
Transaction#: 1316648

Type of Call: 04 Injury Accident  
Callers Name:  
Location : 8010 LANCASTER-NEWARK RD NE

Call Information:

VEH...SEMI VS TRAILER...POWER LINES DOWN...CHILDREN IN RDWY  
SC ANDST..MEDFLIGHT ON STBY AT 1342..START MEDFLIGHT AT 1340..  
TA OF 17 MIN FOR MEDFLIGHT..POLE DOWN..SCP ADV ETA OF 20-30 MIN..  
PA AND EMA ADV AT 1405..MEDFLIGHT OSC AT 1415..ODOT ADV REF TO LIGHTS  
SD1..MEDFLIGHT OFF GROUND AT 1425..ODOT ENR WITH SAND ETA OF 1 HR..  
MURSTON IN CHARGE AT 1431..START EMA AT 1442..EMA 16-15 MIN ETA..

alt#	DIS	ENR	OSC	CLR	LSC	***	INS	INI	COMP	REPORT#
621	13:42	13:42	XX:XX	14:15				14:15		
631	13:42	13:44	13:42	14:30			14:31	14:36		
670	13:42	13:44	13:47	14:31			14:31	14:39		
621	13:42	13:47	13:49	16:04			16:04	16:11		
631	13:42	13:48	13:54	14:38			14:38	14:40		

Postup Transaction(s):

SER DEFINED ENTRY #1 Date: 07/15/04 Time: 13:48:16



FRANKLIN COUNTY SHERIFF  
DISPATCH NARRATIVE

Page 2

07/15/01 Time: 13:26 Dispatcher : D48 Transaction#: 1316648

I WAS IN BACK THE @ 1407...DAPT 621 ADV SIGNAL '0' AT 1620 DSP IN GARAGE  
WITH EMA OFFICE - WERE TOLD ABOUT THE SPILL - WENT UP W/HAZMAT TEAM -  
LED IN A HAZMAT CLEAN-UP COMPANY - THERE WERE NO FATALITIES - 1 INJURY OUT  
THE ACCIDENT/1 TRANSPORTED TO THE HOSPITAL - EMA DID RESPOND - OF PRIMARY  
CERN, WAS THE DIESEL SPILL WHICH IS CURRENTLY BEING CLEANED UP BY A PRIVATE  
TRACTOR WITH EMA SUPERVISING/RELAYED @ 1622  
SP WAS NOTIFIED OF THIS\*\* \*\*ADDITIONAL PRINT-OUT TO THURSTON PD FOR CAPT