B B U Serviceas 4318 Logan Lancaster Rd. Lancaster, Ohio 43130

A L Baucum 9611 Morgan Mill Rd. Monroe North Carolina, 28110

On February 18 th at 21:18 hours B B U Services received a call from Chris Bonner of the Ohio E P A, to notify the on call manager of a call coming from A L Baucum. Ben Cook returned the call to Allan Baucum and was contracted to clean up as needed at the site of his truck accident.

B B U used a vac truck to vac up oil and water that was leaching from the soil below the guard rail post where the fuel oil had entered the ground. B B U then used a back hoe and skid loader to excavate the oil contaminated soil and staged the soil on plastic. B B U then waited till the winch trucks up righted the tractor and trailer then started loading the eggs and crates into dump trucks for transportation to Athens Hocking land fill for disposal. While the dump trucks were being loaded B B U personal finished removing the remainder of the eggs from the trailer. A trachoe was also used to position the

Eggs and fuel oil contaminated soil were disposed of at the Athens Hocking land fill Nelsonville Ohio which was completed February 21 st. 2000.

1000 gallons of fuel oil and water removed from the spill site was disposed of at central Ohio Oil, Marion Rd. Columbus Ohio February 21 st. 2000.

Equipment used on this project.

contaminated soil and eggs for loading.

Three dump trucks.

Three services trucks.

Spill supply trailer.

Generator and light sets.

Cat 416 backhoe.

Geil skid loader.

Kabota trac hoe

3000 gallon vac truck.

Varius hand tools.

Ben H. Cook Sr.