



Emergency Response Section - Initial Pollution Incident Report (IPIR)

10/29/2015

Spill Id Number: 1510-23-2350//0

District: CD

Reported By: KEVIN ROBY
Title: DISP
Telephone: (740) 652-7911 ext:
Affiliation: SHERIFFS OFFICE

Reported: 10/29/2015 12:30
Discovered: 10/29/2015 12:19
Occurred: 00/00/0000
Chronic: N

County: FAIRFIELD
Did Spiller Report ? N
Received By: HOLMES, CHRIS
Local EPC ? N
Business: Y

City/Township: LANCASTER
Complaint ? N
Priority: 3
Did you tell the Spiller to Call the N.R.C ? N
SARA Report: Y

Suspected Spiller: TRAVCO LUMBER CO LLC
Mailing Address: 64511 FRAZEE LN
MCARTHUR, OH 45651
Telephone: (740) 596-5039 ext:

Location: 637 COONPATH RD NE

Source: TRANSPORTATION - TRUCK - ENGINE OR FUEL SUPPLY

Cause: SADDLE TANKS

Reason: ACCIDENT

Waterways Affected: N/A

Media Affected 1: LAND OR LAND SURFACE

Media Affected 2:

Media Affected 3:

Product(s) Spilled

Product	Amount	UOM	RQ	Size	Type	EHS
DIESEL FUEL	100.0	GAL	.0	S	H	N

Other Agencies Notified

Agency	Person	Date	Time
RTK	BEATTIE	10/29/2015	12:41

Remark

APPROX 100 (+) GALS OF FUEL RELEASED AT ABOVE LOCATION. FD IS ATTEMPTING TO KEEP THE FUEL FROM ENTERING A WATER WAY. CHIEF HUTTON WITH PLEASANT TWP FD IS ON SCENE AT 740-215-5116. BOTH SADDLE TANKS AND CROSSOVER LINE HAVE BEEN COMPROMISED. FD IS REQUESTING ASSISTANCE. USDOT# 2491422. OSC KNERR NOTIFIED AT 1240 HOURS.



Rikki Knerr
Emergency Response
Division of Environmental Response
and Revitalization

50 W. Town St., Ste. 700
P.O. Box 1049
Columbus, OH 43216-1049
(614) 728 3825 Cell (614) 395 2129
Rikki.Knerr@epa.ohio.gov
epa.ohio.gov

John R. Kasich, Governor
Craig W. Butler, Director